

Vehicle Service History Report (Consolidated)

Whalen, Jason & Lauren

2013 GMC Truck Yukon XL 1/2 Ton 6.2 L 376 CID V8 Vortec , Vin:1GKS2MEF6DR107597

Labor/Notes

RO #	Item	Category	Tech	Description
7503	ROTATE			Rotate tires and inspect brakes Retrain TPMS All brakes estimated at 40%
7503	SYNTHETIC 4WD			Synthetic Oil Change CHANGE OIL, FILTER AND LUBE SPECIAL: Includes NAPA Gold filter and 6 quarts Full Synthetic motor oil Check all lights Replace left reverse bulb
10072	SYNTHETIC 4WD			Synthetic Oil Change CHANGE OIL, FILTER AND LUBE SPECIAL: Includes NAPA Gold filter and 6 quarts Full Synthetic motor oil Check all lights.
15758	BUFF 17 UP			Buff and Seal aluminum wheel Chrome is peeling off inside of aluminum wheels.
15758	COOLFLUSHFILL	HEATING/COOLI		Flush cooling system and install new antifreeze.
15758	INSPECTION	VISION/SAFETY		SAFETY INSPECTION Inspect all brakes. Front brakes estimated at 10% Rear brakes estimated at 10% Check and adjust tire pressure. Inspect steering and suspension components. U-joints making noise? Remove rear driveshaft and checked both U-joints. Rear was is new and front feels good. Noise was squealer on brake pad rubbing rotor. Inspect belts and hoses. Original but look OK. Check lights, windshield wipers, and washer system. Replace front wiper blades. Check battery, starting, and charging systems. Replace 2012 battery. Top off all fluids. Check and replace engine air filter.
15758	LABOR			Brake maintenance Replace front and rear rotors and pads. Clean and lube brake caliper slides and mounts. Check and adjust parking brake shoes. Check parking brake operation. - OK at this time.
15758	SERVICE TRANS			Service transmission Replace trans filter, pan gasket and clean pan. Exchange fluid and refill. Drain and refill transfer case.

Vehicle Service History Report
(Consolidated)

Whalen, Jason & Lauren

2013 GMC Truck Yukon XL 1/2 Ton 6.2 L 376 CID V8 Vortec , Vin:1GKS2MEF6DR107597

Labor/Notes (continued)

RO #	Item	Category	Tech	Description
15758	SYNTHETIC 4WD			Synthetic Oil Change CHANGE OIL, FILTER AND LUBE SPECIAL: Includes NAPA Gold filter and 6 quarts Full Synthetic motor oil
17747	LABOR			Check oil leak on the right side Found oil leaking from crimped ends of engine oil cooler lines. Check and replace engine oil cooler line set and gasket. Refill engine oil.
17747	ROTATE	TIRE		Rotate tires and inspect brakes Retrain TPMS sensors. Front brakes estimated at 90% Rear brakes estimated at 90% Torque Wheels
17747	SYNTHETIC 4WD			Synthetic Oil Change CHANGE OIL, FILTER AND LUBE SPECIAL: Includes NAPA Gold filter and 6 quarts Full Synthetic motor oil Check all lights.
22772	LABOR			Traction and stabilitrak lights are on Test computer systems and clear codes: C0710 Steering angle sensor signal ckt. C0253 Centering error. C0455 Steering wheel angle sensor performance Replace steering wheel position sensor. Have to R&R steering column to replace.
22772	SYNTHETIC 4WD			Synthetic Oil Change CHANGE OIL, FILTER AND LUBE SPECIAL: Includes NAPA Gold filter and up to 6 quarts full synthetic motor oil. (4WD & AWD)
24653	LABOR			Replace front marker light bulbs Had to remove headlight assemblies to replace bulbs.
24653	LABOR			Replace broken front sway bar links
24653	ROTATE	TIRE		Rotate tires and inspect brakes Front brakes estimated at 30% Rear brakes estimated at 20% Torque Wheels Retrain TPMS sensors.
24653	SYNTHETIC 4WD			Synthetic Oil Change CHANGE OIL, FILTER AND LUBE SPECIAL: Includes NAPA Gold filter and 6 quarts Full Synthetic motor oil Check all lights. Front marker lights are out. Check tire pressures. Check all fluids.

Vehicle Service History Report
(Consolidated)

Whalen, Jason & Lauren

2013 GMC Truck Yukon XL 1/2 Ton 6.2 L 376 CID V8 Vortec , Vin:1GKS2MEF6DR107597

Recommend transmission service.
Lube running boards.

Labor/Notes (continued)

RO #	Item	Category	Tech	Description
26275	LABOR			<p>Check engine light is on</p> <p>Test computer systems (26) and clear codes.</p> <p>P0121 Throttle position sensor 1 performance</p> <p>P0523 Engine oil pressure sensor circuit high voltage</p> <p>C0660 Level control exhaust valve circuit short to ground or open</p> <p>Test and replace engine oil pressure sensor and oil screen/filter</p> <p>Clean throttle plates.</p>
26275	SERVICE TRANS			<p>Service transmission</p> <p>Replace trans filter, pan gasket and clean pan.</p> <p>Exchange fluid and refill.</p> <p>Drain and refill transfer case.</p>
26275	SYNTHETIC 4WD			<p>Synthetic Oil Change</p> <p>CHANGE OIL, FILTER AND LUBE SPECIAL: Includes NAPA Gold filter and up to 6 quarts full synthetic motor oil. (4WD & AWD)</p> <p>Check all fluids.</p> <p>Check tire pressures.</p>
26346	LABOR			<p>Replace rear suspension air compressor</p> <p>Test computer system and clear codes:</p> <p>C0660 level control exhaust valve ckt short to ground or open.</p>
28353	FRONT BRAKES	BRAKES		<p>Front Brake Maintenance</p> <p>Replace front brake pads, rotors, and calipers.</p> <p>Bleed front brakes.</p>
28353	LABOR			<p>Check for oil drips seen under vehicle</p> <p>Rear main seal leaking.</p> <p>Going to need transmission removed for seal replacement.</p> <p>See Estimate</p>
28353	REAR BRAKES	BRAKES		<p>Rear Brake Maintenance</p> <p>Replace rear brake pads, rotors, and calipers.</p> <p>Check and adjust parking brake shoes.</p> <p>Check parking brake operation. - OK at this time.</p> <p>Bleed rear brakes.</p>

Vehicle Service History Report
(Consolidated)

Whalen, Jason & Lauren

2013 GMC Truck Yukon XL 1/2 Ton 6.2 L 376 CID V8 Vortec , Vin:1GKS2MEF6DR107597

Labor/Notes (continued)

RO #	Item	Category	Tech	Description
28353	ROTATE	TIRE		Rotate tires and inspect brakes Retrain TPMS Front brakes estimated at 2mm Rear brakes estimated at 2mm Torque Wheels
28353	SYNTHETIC 4WD			Synthetic Oil Change CHANGE OIL, FILTER AND LUBE SPECIAL: Includes NAPA Gold filter and up to 6 quarts full synthetic motor oil. (4WD & AWD) Check all fluids. Check tire pressures.
29520	ProDemand			Replace leaking rear main seal R&R transmission/transfer case. Remove exhaust Y pipe assembly. Remove rear main seal plate. Replace rear main seal and plate gasket.
29520	SYNTHETIC 4WD			Synthetic Oil Change CHANGE OIL, FILTER AND LUBE SPECIAL: Includes NAPA Gold filter and up to 6 quarts full synthetic motor oil. (4WD & AWD) Check all fluids. Check tire pressures.
30441	LABOR			Check engine light is on Car doesn't want to go. 20MPH Test computer systems and clear codes: P2135: Throttle position sensor 1-2 correlation(sym 00). Test and replace throttle position sensor. Clean and lube throttle body. Perform idle relearn. and cam crank sync.
31496	LABOR			Check running boards Pivot hinges seizing up. Both motors are bad. Would require all pieces to be bought separately from GM and will be very expensive.
31496	LABOR			Check right front tire for leak Tire leaking at bead area. Chromed aluminum wheel in bad shape. Buff and seal right front tire. Replaced valve stem. Balanced tire. Torque wheel. Front brakes at 10mm

Vehicle Service History Report
(Consolidated)

Whalen, Jason & Lauren

2013 GMC Truck Yukon XL 1/2 Ton 6.2 L 376 CID V8 Vortec , Vin:1GKS2MEF6DR107597

Labor/Notes (continued)

RO #	Item	Category	Tech	Description
31496	SYNTHETIC 4WD			Synthetic Oil Change CHANGE OIL, FILTER AND LUBE SPECIAL: Includes NAPA Gold filter and up to 6 quarts full synthetic motor oil. (4WD & AWD) Check all fluids. Check tire pressures.
31557	LABOR			Replace leaking oil pan gasket
31557	LABOR			Replace leaking trans cooler lines
31557	LABOR			Replace leaking power steering lines
31557	LABOR			Check front passenger door handle Replace broken right front outer door handle.
31557	SYNTHETIC 4WD			Synthetic Oil Change CHANGE OIL, FILTER AND LUBE SPECIAL: Includes NAPA Gold filter and up to 6 quarts full synthetic motor oil. (4WD & AWD) Check all fluids. Check tire pressures.
31833	LABOR			Unplug both running boards
31833	LABOR			No start Test and replace battery. Check for battery draw. Drops to .01 after 5-10 minutes after unplugging running board motors.
33305	SYNTHETIC 4WD			Synthetic Oil Change CHANGE OIL, FILTER AND LUBE SPECIAL: Includes NAPA Gold filter and up to 6 quarts full synthetic motor oil. (4WD & AWD) Check all fluids. Check tire pressures. Reset oil life
33305	TRIP	PREVENTATIVE		Check over for trip: Remove all wheels, rotate tires, inspect tires and brakes. Front brakes estimated at 10mm Rear brakes estimated at 8mm Retrain TPMS Torque wheels. Check tire pressures and condition. LF 8/32 RF 8/32 LR 7/32 RR 7/32

Vehicle Service History Report
(Consolidated)

Whalen, Jason & Lauren

2013 GMC Truck Yukon XL 1/2 Ton 6.2 L 376 CID V8 Vortec , Vin:1GKS2MEF6DR107597

Inspect steering and suspension components.
Inspect belts and hoses.
Check lights, windshield wipers, and washer system.
Replaced all three wiper blades.
Check A/C and/or Heat
Check battery, starting, and charging systems.
Test antifreeze. -40°
Check all fluids.

Parts								
RO #	Mfg	Item	Description	Category	QTY	UOM	Condition	
7503	FIL	7060	Oil Filter (Gold)	TUNE UP	1			
7503	LMP	7441	Bulb		1			
7503	MOB	5W30	Full Synthetic 5W30	Parts at List	6			
10072	FIL	7060	Oil Filter (Gold)	TUNE UP	1			
10072	MOB	5W30	Full Synthetic 5W30	Parts at List	6			
15758	-	ANTIFREEZE	Extended life gold antifreeze	Parts at List	9			
15758	-	ATF	Automatic Transmission Fluid	Parts at List	2			
Transfer Case								
15758	-	ATF	Automatic Transmission Fluid	Parts at List	14			
15758	-	DE6L80	Trans filter	Parts at List	1			
15758	-	TIRES	BR 275/55R20/SL DUELER HL		4			
Customer Care Club #20169901								
15758	BAT	7548	BATTERY		1			
15758	BSH	22A	Wiper Blade - Bosch Icon	Parts at List	1			
15758	BSH	22B	Wiper Blade - Bosch Icon	Parts at List	1			
15758	ECH	920145	TPMS valve stem	Parts at List	4			
15758	FIL	2487	Air Filter - NAPA Gold	TUNE UP	1			
IF NEEDED								
15758	FIL	7060	Oil Filter (Gold)	TUNE UP	1			
15758	MOB	5W30	Full Synthetic 5W30	Parts at List	6			
15758	NBK	8312ADK1C	Brake Rotor & Pad Kit - Rear -		1			
Kit includes: 880422CR AD8312								
15758	NBK	8472ADK1C	Brake Rotor & Pad Kit - Front -		1			
Kit includes: 880279CR Rotors AD8472 Pads								
17747	-	20828695	Engine oil cooler line set		1			
17747	FIL	7060	Oil Filter (Gold)	TUNE UP	1			
17747	MOB	5W30	Full Synthetic 5W30	Parts at List	0.5			
Added after lines were changed								

Vehicle Service History Report
(Consolidated)

Whalen, Jason & Lauren

2013 GMC Truck Yukon XL 1/2 Ton 6.2 L 376 CID V8 Vortec , Vin:1GKS2MEF6DR107597

Parts (continued)

RO #	Mfg	Item	Description	Category	QTY	UOM	Condition
17747	MOB	5W30	Full Synthetic 5W30	Parts at List	6		
22772	-	19418403	Steering wheel position sensor		1		
22772	FIL	7060	Oil Filter - NAPA Gold	TUNE UP	1		
22772	MOB	5W30	Full Synthetic 5W30	Parts at List	6		
24653	FIL	7060	Oil Filter (Gold)	TUNE UP	1		
24653	LMP	194NAN	Marker Bulb - Amber		2		
24653	MOB	5W30	Full Synthetic 5W30	Parts at List	6		
24653	NCP	2651206	Sway Bar Link Repair Kit - Front		1		
24653	VAL	975	Qt. Synthetic 75W90 gear oil	Parts at List	0.5		
26275	-	12585328	Oil screen/filter - cylinder		1		
26275	-	12673134	Engine oil pressure sensor		1		
26275	-	ATF	Automatic Transmission Fluid	Parts at List	14	QT	
		Transmission					
26275	-	ATF	Automatic Transmission Fluid	Parts at List	2	QT	
		Transfer case					
26275	-	DE6L80	Trans filter	Parts at List	1		
26275	FIL	7060	Oil Filter - NAPA Gold	TUNE UP	1		
26275	MOB	5W30	Full Synthetic 5W30	Parts at List	6		
26346	ARN	P3242	Suspension Air Compressor		1		
28353	-	BRAKE FLUID	Brake Fluid Dot 3	Parts at List	1		
28353	ADN	12559XA	Brake Caliper (w/ Bracket) -		1		
28353	ADN	12559XB	Brake Caliper (w/ Bracket) -		1		
28353	ADN	12625XA	Brake Caliper (w/ Bracket) -		1		
28353	ADN	12625XB	Brake Caliper (w/ Bracket) -		1		
28353	FIL	7060	Oil Filter - NAPA Gold	TUNE UP	1		
28353	FLT	FT8312	Brake Pads - Rear - Fleet		1		
		Warranty					
28353	MOB	5W30	Full Synthetic 5W30	Parts at List	6		
28353	NBK	8472ADK1C	Brake Rotor and Pad Kit - Front		1		
		Warranty					
		Kit includes:					
		880279CR Rotors					
		AD8472 Pads					
28353	UP	880422CR	Brake Rotor - Rear - Adaptive		2		
		Warranty					
29520	FIL	7060	Oil Filter - NAPA Gold	TUNE UP	1		
29520	FPG	BS40640	Rear Main Seal Kit		1		
29520	MOB	5W30	Full Synthetic 5W30	Parts at List	6		
30441	-	19259452	Throttle position sensor kit	Parts at List	1		
31496	ECH	920145	TPMS valve stem	Parts at List	1		
31496	FIL	7060	Oil Filter - NAPA Gold	TUNE UP	1		
31496	MOB	5W30	Full Synthetic 5W30	Parts at List	6		

Vehicle Service History Report
(Consolidated)

Whalen, Jason & Lauren

2013 GMC Truck Yukon XL 1/2 Ton 6.2 L 376 CID V8 Vortec , Vin:1GKS2MEF6DR107597

Parts (continued)

RO #	Mfg	Item	Description	Category	QTY	UOM	Condition
31557	-	12584922	Oil pump O ring		1		
31557	-	12612350	Oil pan gasket		1		
31557	-	15203889	Engine oil cooler line gasket		1		
31557	-	15779543	Auxillary trans cooler line	Parts at List	1		
31557	-	25999420	Trans oil cooler line set		1		
31557	FIL	7060	Oil Filter - NAPA Gold	TUNE UP	1		
31557	MOB	5W30	Full Synthetic 5W30	Parts at List	6		
31557	NOE	7356526	Door Handle - Exterior		1		
31557	NPS	76625	Power Steering Return Hose -		1		
31557	NPS	76776	Power Steering Pressure Hose		1		
31833	BAT	7548	BATTERY	Parts at List	1		
33305	BSH	4822	Wiper Blade	Parts at List	2		
33305	FIL	7060	Oil Filter - NAPA Gold	TUNE UP	1		
33305	MOB	5W30	Full Synthetic 5W30	Parts at List	6		
33305	WIP	6012E	Wiper Blade - rear	Parts at List	1		