

Vehicle Inspection Form

Vehicle ID	5358				
Year	2012	Manufacture	HONDA	Model ID	CIVIC
VIN:	JHMFB4F23CS007455				Title Clear <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No

Vehicle Passes Safety Inspection **Vehicle Has Major Defects Sold "As Salvage"**

Mileage/ Odometer: 94,867	Hours: <input checked="" type="checkbox"/> NA	Accurate <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
----------------------------------	---	--

Engine Description	1.5L HYBRID	<input type="checkbox"/> NA	Fuel Type	<input checked="" type="checkbox"/> Unleaded	<input type="checkbox"/> Diesel	<input type="checkbox"/> Other
--------------------	--------------------	-----------------------------	-----------	--	---------------------------------	--------------------------------

General:

Starts Starts With Boost NA Trailer or Other

Runs Does Not Run Scrap\Salvage\Parts Only

Condition Unknown

Transmission: Automatic Manual Number of Speeds

Transmission Condition: Operable Needs Repair Unknown NA Trailer or Other

Drivetrain: Rear Wheel Drive Front Wheel Drive All Wheel Drive 4 Wheel Drive

Working Condition Yes No Unknown NA Trailer of Other

Exterior: Color **GRAY** Minor Damage Dents Dings Scratches

See Photos Major Damage Yes No

Decals Removed Yes No





Impressions\Residue From Decals Yes No NA

Review all Auction Equipment Photos Carefully

Windows: No Cracked or Broken Glass
 Damaged Glass

Emergency Equip Removed Yes No NA

Equip Removal Holes in Vehicle Yes No NA

Interior: Color **GRAY/TAN** Upholstery Cloth Vinyl Leather
 Flooring Carpet Vinyl

Interior Condition Issues: **SILICONE ON DASH AND IN THE CENTER CONSOLE. HOLES IN THE CENTER CONSOLE.**

Equipment Radio Type AM AM-FM Cassette CD Other
 Air-Bags Yes No Driver's Dual Side or other
 Air Conditioning Yes No Dual AC Cold Inoperative
 Options Tilt Steering Cruise Control Dual Climate Control Other
 Power Options Windows Door Locks Remote Mirrors Seat(s)

Tire and Wheels: Number of Tires **4** Spare Tire Yes No
 Special Rims Yes No All Tires Meet Safety Standards Yes No

Know Repairs Needed:

Engine Repairs Leaks Oil Leaks Coolant Other

Description: **NONE NOTED**

Know Repairs Needed:

Transmission Repairs Leaks Oil Other

Description: **DELAY WHEN SHIFTING INTO REVERSE OR DRIVE.**

Know Repairs Needed:

Drivetrain Repairs Leaks Oil Other

Description: **NONE NOTED**

Know Repairs Needed:

Suspension\Brakes Repairs Other

Description: **NONE NOTED**

Know Repairs Needed Other:

Description: **THE A/C IS NOT WORKING, THE PAINT IS PEELING ON THE HOOD, THE ROOF AND THE TRUNK LID.THERE IS CHIPS IN THE FRONT AND REAR BUMPERS. THERE IS A DING NEXT TO THE FUEL DOOR. THE DRIVERS SIDE EXTERIOR MIRROR IS BROKEN.**

Vehicle Maintained BY: County of Santa Barbara Other

Technician ID **54**