

# PLAT OF SURVEY

## SURVEYOR'S REPORT

Survey for Jane E. Rose  
Tract owner/sy C. Rose  
Basis of bearing: Assumed WGS84  
Field work performed on: 10/10/18

As required by Title 655, I.C.: 12-7-8 the acceptable relative  
directional accuracies of the corners of the subject tract  
established in this survey is within the specifications for a  
surveyor's work, which is a relative positional accuracy of 0.13  
feet plus 1/10 parts per million.

The basis of bearing for this re-measurement is assumed, and the  
basis of bearing for the desired description is unknown, but  
desired bearings and distances are shown herein.

Lines 170-162-161-160-175-170-177-176-175 were established  
per the client's request, plus the approximate centerline of  
County Road 200 North.

Lines 175-171-160-173-150 were established at specific on site  
locations of 171, 160, 173, per client's request.

There may be unwritten usage or ownership rights when dealing  
with, but not limited to, mow lines, fence lines, or tree lines.

Sign of use by adjacent neighbor may include, but not limited to,  
new items, fence lines, tree lines, big houses, gardens, hiking  
trails, walking trails, etc.

Subject to all easements, right-of-ways and restrictions of  
record.

This survey does not certify compliance with building and zoning  
restrictions or suitability of the property for any particular purpose.

As a result of the above observations, it is my opinion that the  
uncertainties in the location of the lines and corners established  
in this survey are as follows:

Due to Availability and condition of reference monuments: See  
own legend.

Due to Occupation or Possession lines: See drawing.

Due to Clarity or ambiguity of the record description used and of  
adjacent's description and the relationship of the lines of the  
subject tract with adjacent's lines. See report above.

Annotations, found or set in rural, season and areas, is  
typically +/- 0.4' above the ground. Monumentation found or set,  
in urban, frequently used areas is typically +/- 0.2' below  
ground level. See point legend for more information.

I wish to certify that this survey was made by me or under my  
supervision and that this plat represents said survey. I do not  
relate to the determination of ownership. This survey is subject  
to other factors that may be induced by a full and accurate title  
search.

This survey, to the best of my knowledge and belief, is executed  
according to Official Records available to me.

RECORDED BY: JANE E. ROSE  
ARMONI: HENDRICKS I.D. & SURVEYS

Point Legend  
No. 20500003016 STATE OF INDIANA SURVEYOR

