

## Certificate of Analysis

Report Date: September 15, 2017  
Sample ID#: 17-0824  
Client: Ritzy Realty


Property Tested: 1545 Deerfield Road  
Darlington, MD 21034

County: Harford  
Sampler ID: 5226SB  
Collection Location: Hall Bathroom Tap  
Date/Time Collected: 9/14/17 at 11:25 am  
Date/Time Relinquished: 9/14/17 at 2:35 pm

The following equipment  
appears to be installed-  
Conditioning/Treatment: Sediment Filter  
Well Tag Number: Not Visible  
Well Condition: 1 piece cap

Samples Iced: Yes  
Residual  $CL_2 < 0.1$  mg/L: Yes

<u>Test Parameter:</u>	<u>Method:</u>	<u>^MCL/*SMCL:</u>	<u>Result:</u>	
Nitrate as N	SM 4500D	10 mg/L as N	7.1 mg/L as N	PASS
Turbidity	EPA 180.1	10 NTU	5.4 NTU	PASS
pH	EPA 150.1	*6.5-8.5 Units	6.0 Units	**
Sand		Negative	Negative	
Total Coliform	SM 9223B	Absent	Absent	PASS
E. Coli	SM 9223B	Absent	Absent	PASS

  
\_\_\_\_\_  
Kristy (Caswell) Whipperman  
MD Lab 328

<sup>^</sup>MCL- Maximum Contamination Level

<sup>\*</sup>SMCL- Secondary Maximum Contamination Level

<sup>\*\*</sup>A non-enforceable parameter that may cause cosmetic or aesthetic effects (such as taste, color, or odor) in drinking water.

Based upon Coliform Bacteriological Standards, the above results indicate that, at the time the sample was collected, this water sample was safe for drinking purposes.

Caswell Testing & Water Systems, LLC  
Phone: 410-557-9355

21429-A York Road  
email: [caswelltesting@verizon.net](mailto:caswelltesting@verizon.net)  
MWD 320 MD Lab 328

Freeland, MD 21053  
fax: 410-357-5483