

Lot # 1



Macomb Community Action Head Start School Bus Inspection Report School Year (2020-2021)

QR Code 20287 Bus Number 219 Vehicle Identification Number 1GB3G3BL2E1205293

Year 2014 Make Chevrolet Mileage 34027

Model THOMAS Inspection Start Time 1250 Inspection End Time 1314

Seating Capacity 21 - 40 Complaint Number N/A

Contractor / Dealer N/A Inspection Type Annual

Engine Type Diesel

Address 44900 VIC WERTZ

City CLINTON TOWNSHIP

State MICHIGAN Zip 48036 County Macomb

Push Rod Travel

Axle1 Left: N/A Axle1 Right: N/A

Axle2 Left: N/A Axle2 Right: N/A

TRIP Value: N/A

Violations	Tag	Comments	Date Fixed
No Violations			

** This violation indicates a "RED" sticker vehicle condition, as described in 257.1041(2). ALL violations listed must be documented as repaired before a Michigan vehicle passing sticker is affixed to the vehicle windshield.*

Inspection Tag: **PASS**

Comments:

Inspected By: J Clark

Inspection Date: Thursday, September 17, 2020



Macomb Community Action Head Start School Bus Inspection Report School Year (2020-2021)

QR Code 21467 Bus Number 221 Vehicle Identification Number 4DRAPSKK5AB136829

Year 2010 Make Genesls, International Mileage 74208

Model Inspection Start Time 1352 Inspection End Time 1410

Seating Capacity 21 - 40 Complaint Number N/A

Contractor / Dealer N/A Inspection Type Annual

Engine Type Diesel

Address 44900 VIC WERTZ

City CLINTON TOWNSHIP

State MICHIGAN Zip 48036 County Macomb

Push Rod Travel

Axle1 Left: N/A Axle1 Right: N/A

Axle2 Left: N/A Axle2 Right: N/A

TRIP Value: N/A

Violations	Tag	Comments	Date Fixed
No Violations			

* This violation indicates a "RED" sticker vehicle condition, as described in 257.1841(2). ALL violations listed must be documented as repaired before a Michigan vehicle passing sticker is affixed to the vehicle windshield.

Inspection Tag: **PASS**

Comments:

Inspected By: J Clark

Inspection Date: Thursday, September 17, 2020

Lot # 4



Macomb Community Action Head Start School Bus Inspection Report School Year (2020-2021)

QR Code 00693 Bus Number 222 Vehicle Identification Number 1GB3G3BL7F1288010

Year 2015 Make Chevrolet Mileage 20361

Model MINOTOUR Inspection Start Time .1212 Inspection End Time 1237

Seating Capacity 21 - 40 Complaint Number N/A

Contractor / Dealer N/A Inspection Type Annual

Engine Type Diesel

Address 44900 VIC WERTZ

City CLINTON TOWNSHIP

State MICHIGAN Zip 48036 County Macomb

Push Rod Travel

Axle1 Left: N/A Axle1 Right: N/A

Axle2 Left: N/A Axle2 Right: N/A

TRIP Value: N/A

Violations	Tag	Comments	Date Fixed
No Violations			

* This violation indicates a "RED" sticker vehicle condition, as described in 257.1841(2). ALL violations listed must be documented as repaired before a Michigan vehicle passing sticker is affixed to the vehicle windshield.

Inspection Tag: **PASS**

Comments:

Inspected By: J Clark

Inspection Date: Thursday, September 17, 2020



Macomb Community Action Head Start School Bus Inspection Report School Year (2020-2021)

QR Code	21465	Bus Number	227	Vehicle Identification Number	1GD373BL2B1103057
Year	2011	Make	GMC	Mileage	73742
Model		Inspection Start Time	928	Inspection End Time	950
Seating Capacity	21 - 40	Complaint Number	N/A		
Contractor / Dealer	N/A	Inspection Type	Annual		
Engine Type	Diesel				

Address 44900 VIC WERTZ

City CLINTON TOWNSHIP

State MICHIGAN Zip 48036 County Macomb

Push Rod Travel

Axle1 Left: N/A Axle1 Right: N/A

Axle2 Left: N/A Axle2 Right: N/A

TRIP Value: N/A

Violations	Tag	Comments	Date Fixed
No Violations			

** This violation indicates a "RED" sticker vehicle condition, as described in 257.1041(2). ALL violations listed must be documented as repaired before a Michigan vehicle passing sticker is affixed to the vehicle windshield.*

Inspection Tag: **PASS**

Comments:

Inspected By: J Clark

Inspection Date: Thursday, September 17, 2020

Lot #7



Macomb Community Action Head Start School Bus Inspection Report School Year (2020-2021)

QR Code 21475 Bus Number 228 Vehicle Identification Number 1GD373BL6B1102901

Year 2011 Make GMC Mileage 71713

Model Inspection Start Time 030 Inspection End Time 051

Seating Capacity 21 - 40 Complaint Number N/A

Contractor / Dealer N/A Inspection Type Annual

Engine Type Diesel

Address 44900 VIC WERTZ

City CLINTON TOWNSHIP

State MICHIGAN Zip 48036 County Macomb

Push Rod Travel

Axle1 Left: N/A Axle1 Right: N/A

Axle2 Left: N/A Axle2 Right: N/A

TRIP Value: N/A

Violations	Tag	Comments	Date Fixed
No Violations			

** This violation indicates a "RED" sticker vehicle condition, as described in 257.1841(2). ALL violations listed must be documented as repaired before a Michigan vehicle passing sticker is affixed to the vehicle windshield.*

Inspection Tag: **PASS**

Comments:

Inspected By: J Clark

Inspection Date: Thursday, September 17, 2020

LOT # 8



Macomb Community Action Head Start School Bus Inspection Report School Year (2020-2021)

QR Code 21463 Bus Number 229 Vehicle Identification Number 1GD373BL7B1103474

Year 2011 Make GMC Mileage 74441

Model Inspection Start Time 901 Inspection End Time 920

Seating Capacity 21 - 40 Complaint Number N/A

Contractor / Dealer N/A Inspection Type Annual

Engine Type Diesel

Address 44900 VIC WERTZ

City CLINTON TOWNSHIP

State MICHIGAN Zip 48036 County Macomb

Push Rod Travel

Axle1 Left: N/A Axle1 Right: N/A

Axle2 Left: N/A Axle2 Right: N/A

TRIP Value: N/A

Violations	Tag	Comments	Date Fixed
No Violations			

* This violation indicates a "RED" sticker vehicle condition, as described in 257.1841(2). ALL violations listed must be documented as repaired before a Michigan vehicle passing sticker is affixed to the vehicle windshield.

Inspection Tag: **PASS**

Comments:

Inspected By: J Clark

Inspection Date: Thursday, September 17, 2020